

2x2, 1x4 & 2x4 Surface Mounted Frame Installation Instructions

1. Turn off power to location where fixture is to be mounted
2. Rotate all the hanging tabs on the fixture so the bent section of the hanging tab is toward the center of the fixture
3. Locate ceiling mounting hole locations
4. Transfer measurements to the horizontal frame members
5. Drill mounting holes in horizontal frame members if needed
6. Mount frame to ceiling using appropriate bolts / screws (supplied by others) – Minimum size recommended is ¼ - 20 moly bolt or ¼ lag screw with washers as needed
7. Connect electrical whip (supplied by others) to fixture. Connect dimming wires if this function is used.
8. Open one end cap on frame
9. Slide fixture into the open side of the frame with enough space to access the ceiling electrical junction box
10. Connect the fixture whip wires to the electrical junction box wires
11. Connect hanging chain / wire (supplied by others) to ceiling hook or frame member to support fixture
12. Slide fixture completely into frame
13. Close open side end cap and secure with 2 screws on both sides
14. Turn power back on
15. Enjoy the evenly distributed LED light

Sample: 2x2 Drawing Surface Mounted Frame



2x2 Frame Dimensions
24.45" X 24.45" X 3.5"

Additional Sizes

2x4 Frame Dimensions
48.31" X 24.45" X 3.5"

1x4 Frame Dimensions
12.45" X 48.31" X 3.5"

Other sizes upon request.



ORDERING INFORMATION

Frame	SMF	22	W
Brand	Model	Size	Powder Coated
	Surface Mounted	22 - 2'x2'	W White
	Frame	12 - 1'x4'	
		24 - 2'x4'	